

# Release Notes BtlViewer Version 4

ID	Summary	Date	Version	Area	Type
65	Drilling, drag & drop must be a cut-paste, not a copy-paste	31.01.2012	4.0.416		Bug
116	Group of drilling can be not deleted with drag and drop	31.01.2012	4.0.407	Single Member Treeview	Bug
111	010 Length cut, add a control to P11 : error if P11=0	09.01.2012	4.0.370	Single Member	Bug
92	New attributes for a part: GRAINDIRECTION and REFERENCESIDE	22.12.2011	4.0.372	Single Member	Feature
105	G-016-X Slot: new definition for limits of edges	19.12.2011	4.0.370	Single Member	Feature
112	010 Length cut, new Parameter P04	19.12.2011	4.0.370	single member	Feature
101	New parameter RANGE in section [GENERAL]	12.12.2011	4.0.360	Single Member	Feature
108	Crash by opening since the version 4.0.248	05.12.2011	4.0.355	transformation	Bug
106	Graphic settings standard updated	01.12.2011	4.0.351	Single Member	Bug
88	G-012-X Ridge or Valley Cut: Angles P13 - P16 in faces.	01.12.2011	4.0.351		Feature
87	G-010-X Longitudinal Cut: Angles P13 and P14 in face	01.12.2011	4.0.351		Feature
99	BUILD VERSION should be shown right down.	29.11.2011	4.0.439	User Interface	Feature
91	Dovetail tenon and mortise: Additional definition of P12 (diameter)	29.11.2011	4.0.349	1/2/3/4-055	Feature
90	3/4-030-X Half Lap: New definition of P04 for limits	29.11.2011	4.0.350	single member	Feature
107	Sägenut 3-013-X	21.11.2011			Bug
95	PROCESSKEY 010 P06 negativ should be vorbiden	24.10.2011	4.0.300	single member	Bug
94	PROCESSKEY 060 Text crashes the BTL Viewer	24.10.2011	4.0.299	single member	Bug
61	New CF in BTL 10.5 = 4-061 (text)	20.10.2011	4.0.294	Single Member	Feature
83	Plausibility by PROCESSKEY X-250-X & NAIL CONTOUR modelisation	12.10.2011	4.0.276		Bug
46	Plausibility Control : Warning when you change a Parameter	06.10.2011	4.0.275	check btl file	Feature
76	Warning if UID comes 2 times	05.10.2011	4.0.273	open	Bug
58	UIDs by part should be also shown	05.10.2011	4.0.273	single member	Feature
85	autoupdate, version Full	05.10.2011	4.0.270		Bug
48	Control Plausibility, 030 Lap Joint P13	03.10.2011	4.0.271	parameter	Bug
47	Control Plausibility, drilling 3-040	03.10.2011	4.0.271	Parameter	Bug
84	Crash with the separate characters thousands in	30.09.2011	4.0.269	write xam	Bug

82	regionals parameters Plausibility by OUTLINE	28.09.2011	4.0.267	Stability	Bug
81	Unknown PROCESSKEY should be detected	27.09.2011	4.0.266	btl file checking	Bug
80	Compatibility with BTL version 10.5	26.09.2011	4.0.263	stability	Bug
8	PROCESSKEY G-106-X bitmap are missing	19.09.2011	4.0.250	Help	Bug
54	TEXTUR for Startoffset and Endoffset is wrong	19.09.2011	4.0.258		Bug
78	Add Help Bitmap for reference Plane	16.09.2011	4.0.255		Usability
77	PROCESSKEY 051 Mortise Front P14 and P15 should be limited to +/- 50000 instead of +/- 1000	06.09.2011	4.0.241	Processkey 051	Bug
74	General, viewer is crashing with russian text	06.09.2011	4.0.242	Read Xam	Bug
72	Parts and panels optimization, compatibility with Boole and Partners	05.08.2011			Feature
66	move the new parameter "autozoom"	05.08.2011	4.0.203	common settings	Usability
59	Add the Help Bitmaps for a group of CF	04.08.2011	4.0.202	single member	Feature
57	Theparameters move if I select a CF with the focus in the reference Side	04.08.2011	4.0.202	single member	Bug
24	Wrong Bitmap when I am in the KF	04.08.2011	4.0.201	single member	Bug
67	Part Dimension Controll is too hard: height = 0.5 mm should be allowed (folie)	21.07.2011	4.0.185		Bug
64	Nesting, Optimierung, UID	12.07.2011	4.0.175		Bug
63	BTL Viewer clasch, seems a problem with UID	12.07.2011	4.0.175		Bug
31	Help Bitmap by FC 106 and 136.		4.0.162		Bug
16	Zapfenloch P04	21.06.2011	4.0.146	General	Bug
36	Ordering of diameter for drillings	21.06.2011	4.0.146		Feature
29	with a drilling group, the CF sorting is false	21.06.2011	4.0.146		Bug
60	Extend the Table for the new Parameter P16 To P22	21.06.2011	4.0.146	single member	Bug
55	PROCESSKEY 250; P03 can not be modify since V4.0.87	20.06.2011	4.0.144	Individual part	Bug
37	0250 Reference plan by startpoint is not for the whole contour	20.06.2011	4.0.145	Single Member	Bug
53	3-051 P04 and P10 missing	15.06.2011	4.0.140		Bug
38	Copying in Individual part not working correctly, drag and drop also	09.06.2011	4.0132	single member	Bug
25	PROCESSKEY 106 plausibility should accept P14=0	09.06.2011	4.0.133	Processing 106	Bug
9	PROCESSKEY 0300 by adding a new subordinated part, the processes are not shown	08.06.2011	4.0.113		Bug
56	RAWPART turning a subpart does not work	27.05.2011	4.0.120		Bug
52	Nesting, Display of Processings of subparts		4.0.120	Individual part	Bug
44	SetUp BTIVIEWER V4, the BTL files are not recognise		4.0.84	setup	Bug
	Registration of BTL file is not possible after				

45	installatioin	05.05.2011	4.0.89	Settings	Bug
10	BTL viewer and BTL Editor should have the teamviewer	04.05.2011	4.0.87	Remote	Feature
49	Error Report should be implemented	04.05.2011	4.0.87	Error Report	Feature
34	Install: the path for BTL ini-files should be free	08.03.2011	4.0.28	Setup	Feature
23	Free reference plane: the reference side should be also free	23.02.2011	4.0.8	Single Member	Bug
22	Warning messages should be resum in one message	15.11.2010	3.0.441		Bug